Concord Public Schools FY18 - FY22 Identified Capital Needs

Project Description	FY18	FY19	FY20	FY21	FY22	Comments / Building Total
Alcott	00.000					
ERU Replacement	20,000					Planned replacement of equipment
Replacement of stairwell Floor covering	40,000			150.000		Covering is worn and in need of replacement
VCT Replacement through facility				150,000		VCT is lifting from slab throughout the facility
Parking Area Sealing & Relining				20,000		
New lead condensing boiler and controls				175,000		Per 2013 National Grid Energy Audit - Original Boiler w/b redundant backup
New lighting improvements	75,000					Per 2013 National Grid Energy Audit
Total Alcott	135,000	0	0	345,000	0	\$480,000
Thoreau						
Sidewalk replacement	140,000	35,000				Sidewalk is spalling and decaying in front of the facility
Heat trace for Sloped roofs to prevent ice damming	,	55,000				
Classroom & Hall Painting		,- 50			75.000	
New lead condensing boiler and controls						Per 2013 National Grid Energy Audit - Original Boiler w/b redundant backup
New lighting improvements		65,000				
Total Thoreau	140,000	155,000	0	0	170,000	\$295,000
Carpet Replacement		25,000	25,000			Carpet is in need of repalcement in various rooms due to use
Willard Carpet Replacement Willard Fields Irrigation & Reseeding	200,000	25,000	25,000			Carpet is in need of repalcement in various rooms due to use
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs	200,000		25,000			Carpet is in need of repalcement in various rooms due to use Repair damaged concrete walks
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot		9,500	15,000			Repair damaged concrete walks
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs	200,000		,	0	0	Repair damaged concrete walks
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot Total Willard		9,500	15,000	0	0	Repair damaged concrete walks
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot Total Willard Peabody Building		9,500	15,000	0	0	Repair damaged concrete walks \$274,500
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot Total Willard Peabody Building Facility Assessment		9,500	15,000	0	0	Repair damaged concrete walks \$274,500 Audit of Facility for Capital Needs
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot Total Willard Peabody Building Facility Assessment Installation of new exhaust unit for classrooms Replacement of HVAC controls and unit ventilator throughout school-design phase followed by		9,500	15,000	0		Repair damaged concrete walks \$274,500
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot Total Willard Peabody Building Facility Assessment Installation of new exhaust unit for classrooms Replacement of HVAC controls and unit ventilator throughout school-design phase followed by construction		9,500 34,500 650,000	15,000	0		Repair damaged concrete walks \$274,500 Audit of Facility for Capital Needs Planned replacement of unit HVAC systems starting to fail due to age of equipment.
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot Total Willard Peabody Building Facility Assessment Installation of new exhaust unit for classrooms Replacement of HVAC controls and unit ventilator throughout school-design phase followed by construction Domestic water piping replacement		9,500 34,500	15,000	0		Repair damaged concrete walks \$274,500 Audit of Facility for Capital Needs Planned replacement of unit HVAC systems starting to fail due to age of equipment. Replacement due to age of piping in crawl spaces.
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot Total Willard Peabody Building Facility Assessment Installation of new exhaust unit for classrooms Replacement of HVAC controls and unit ventilator throughout school-design phase followed by construction Domestic water piping replacement General flooring replacement		9,500 34,500 650,000 450,000	15,000 40,000	0		Repair damaged concrete walks \$274,500 Audit of Facility for Capital Needs Planned replacement of unit HVAC systems starting to fail due to age of equipment. Replacement due to age of piping in crawl spaces. Wear and tear of flooring
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot Total Willard Peabody Building Facility Assessment Installation of new exhaust unit for classrooms Replacement of HVAC controls and unit ventilator throughout school-design phase followed by construction Domestic water piping replacement Electrical power upgrade for technology		9,500 34,500 650,000 450,000	15,000	0		Repair damaged concrete walks \$274,500 Audit of Facility for Capital Needs Planned replacement of unit HVAC systems starting to fail due to age of equipment. Replacement due to age of piping in crawl spaces. Wear and tear of flooring Lack of electrical power for increased demand for power.
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot Total Willard Peabody Building Facility Assessment Installation of new exhaust unit for classrooms Replacement of HVAC controls and unit ventilator throughout school-design phase followed by construction Domestic water piping replacement Electrical power upgrade for technology Partitions for Classrooms		9,500 34,500 650,000 450,000 250,000	15,000 40,000	0		Repair damaged concrete walks \$274,500 Audit of Facility for Capital Needs Planned replacement of unit HVAC systems starting to fail due to age of equipment. Replacement due to age of piping in crawl spaces. Wear and tear of flooring
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot Total Willard Peabody Building Facility Assessment Installation of new exhaust unit for classrooms Replacement of HVAC controls and unit ventilator throughout school-design phase followed by construction Domestic water piping replacement General flooring replacement Electrical power upgrade for technology Partitions for Classrooms Master clock system		9,500 34,500 650,000 450,000 250,000	15,000 40,000	0		Repair damaged concrete walks \$274,500 Audit of Facility for Capital Needs Planned replacement of unit HVAC systems starting to fail due to age of equipment. Replacement due to age of piping in crawl spaces. Wear and tear of flooring Lack of electrical power for increased demand for power. Replace due to age of equipment.
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot Total Willard Peabody Building Facility Assessment Installation of new exhaust unit for classrooms Replacement of HVAC controls and unit ventilator throughout school-design phase followed by construction Domestic water piping replacement General flooring replacement Electrical power upgrade for technology Partitions for Classrooms Master clock system Exterior paint removal under canopies		9,500 34,500 650,000 450,000 250,000 295,000	15,000 40,000	0		Repair damaged concrete walks \$274,500 Audit of Facility for Capital Needs Planned replacement of unit HVAC systems starting to fail due to age of equipment. Replacement due to age of piping in crawl spaces. Wear and tear of flooring Lack of electrical power for increased demand for power. Replace due to age of equipment. Sand blasting is required non lead / non mercury paint
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot Total Willard Peabody Building Facility Assessment Installation of new exhaust unit for classrooms Replacement of HVAC controls and unit ventilator throughout school-design phase followed by construction Domestic water piping replacement General flooring replacement Electrical power upgrade for technology Partitions for Classrooms Master clock system Exterior paint removal under canopies Exterior repairs, caulking masonry repairs		9,500 34,500 650,000 450,000 250,000 295,000 120,000 125,000	15,000 40,000			Repair damaged concrete walks \$274,500 Audit of Facility for Capital Needs Planned replacement of unit HVAC systems starting to fail due to age of equipment. Replacement due to age of piping in crawl spaces. Wear and tear of flooring Lack of electrical power for increased demand for power. Replace due to age of equipment.
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot Total Willard Peabody Building Facility Assessment Installation of new exhaust unit for classrooms Replacement of HVAC controls and unit ventilator throughout school-design phase followed by construction Domestic water piping replacement General flooring replacement Electrical power upgrade for technology Partitions for Classrooms Master clock system Exterior paint removal under canopies Exterior repairs, caulking masonry repairs Energy improvements lighting		9,500 34,500 650,000 450,000 250,000 295,000 120,000 125,000 70,000	15,000 40,000			Repair damaged concrete walks \$274,500 Audit of Facility for Capital Needs Planned replacement of unit HVAC systems starting to fail due to age of equipment. Replacement due to age of piping in crawl spaces. Wear and tear of flooring Lack of electrical power for increased demand for power. Replace due to age of equipment. Sand blasting is required non lead / non mercury paint
Carpet Replacement Willard Fields Irrigation & Reseeding Walk way repairs Crack seal parking lot Total Willard Peabody Building Facility Assessment Installation of new exhaust unit for classrooms Replacement of HVAC controls and unit ventilator throughout school-design phase followed by construction Domestic water piping replacement General flooring replacement Electrical power upgrade for technology Partitions for Classrooms Master clock system Exterior paint removal under canopies Exterior repairs, caulking masonry repairs		9,500 34,500 650,000 450,000 250,000 295,000 120,000 125,000	15,000 40,000			Repair damaged concrete walks \$274,500 Audit of Facility for Capital Needs Planned replacement of unit HVAC systems starting to fail due to age of equipment. Replacement due to age of piping in crawl spaces. Wear and tear of flooring Lack of electrical power for increased demand for power. Replace due to age of equipment. Sand blasting is required non lead / non mercury paint

Concord Public Schools FY18 - FY22 Identified Capital Needs

Project Description	<u>FY18</u>	<u>FY19</u>	<u>FY20</u>	<u>FY21</u>	<u>FY22</u>	Comments / Building Total
Comb one Duilding						
Sanborn Building						
Facility Assessment						Audit of Facility for Capital Needs
Railing installation in center courtyard						Safety issue, railing will prevent possible fall from courtyard
Main Lobby quary tile replacement						Replace flooring due to loose and delaminating tiles
Modular for two classrooms		050.000				The cost includes complete installation with design fees
Asbestos abatement / classrooms		250,000				VAT tile should be abated as soon as possible. This request for is for
						all classrooms where asbestos tile is covered by degraded carpets an
Marta de la composición		00.000				any remaining VAT.
Master clock system		20,000	450.000			Install new wireless clock system for facility
Fire alarm detection			150,000	050.000		Upgrade to an addressable fire alarm system
Domestic water piping replacement		390,000		250,000		Replacement of old piping
HVAC equipment replacement		1,025,000 1,500.000				
Roof replacement Energy improvements lighting		,,				
Upgrade portable buildings		120,000			1,400,000	
Total Sanborn	\$0	\$3,305,000	\$150.000	\$250.000	\$1,400,000 \$1,400,000	
	ΨΟ	\$5,505,000	\$150,000	\$230,000	\$1,400,000	φ4,220,000
Ripley Building						
Innovation STEAM Lab	300,000					CPS contribution towards CPA & Other Funds towards \$300K project
Integrated PreSchool Playground Partnership	75,000					
Exterior door replacement		21,000				Preschool and CCC
Paving Parking lot		64,350				
Domestic water piping replacement		450,000				Antiquated 1950's and early 60's piping
Boiler and HVAC equipment replacement		450,000	300,000			Antiquated 1950's and early 60's equipment
Exterior door replacement Admin				57,600		
Replace flooring throughout		320,000				Removal of and replacement of Vinyl Asbestos Flooring
Exterior repairs, repointing		75,000				
Lighting improvements		60,000				Energy audit recommendation
Install connection to sewer system				250,000		Connect the building to town sewer due to aging 1955 septic system
Window replacement Insulation				75,000		Energy audit recommendation
Total Ripley	\$375,000	\$1,440,350	\$300,000	\$382,600	\$0	\$2,497,950
Yearly Totals	\$850,000	\$7,044,850	\$1,560,000	\$977,600	\$1,570,000	\$11,002,450

\$ 850,000 \$ 900,000 \$ 950,000 \$ 1,000,000