
### ALCOTT ERU ENERGY WHEEL REPLACEMENT



# ALCOTT ERU ENERGY WHEEL REPLACEMENT

 The ERU'S are currently designed as 100% outdoor air units. If the energy recovery wheel fails the unit cannot maintain the proper discharge air temperatures. The energy wheels will be replaced to ensure proper operation.


# RIPLEY STEAM LAB Proposed layout



#### INTEGRATED PRESCHOOL PLAYGROUND (CURRENT)



# INTEGRATED PRESCHOOL PLAYGROUND PLAN (PROPOSED)



#### THOREAU SIDEWALK REPAIR / REPLACEMENT Sidewalks are decaying posing a safety hazard



### THOREAU SIDEWALK REPAIR/REPLACEMENT Sidewalks are decaying posing a safety hazard



WILLARD FIELD RENOVATIONS Renovate the playground and install irrigation for maintenance purposes.

