

DESIGN SUB COMMITTEE 9.14.2021


FLOOR PLAN UPDATES











UPPER-LEVEL PLAN




















PREVIOUSLY PRESENTED













INTERIOR FINISHES






Interior materials will be selected conscious of the projects budget, sustainability and long-term building maintenance goals.

The interior design will relate to the exterior design and palette. Glazing on the exterior will create a visual and physical connection to the interior.


The building has been designed to encourage student engagement within academic clusters and common areas. Patterns, colors and materials will provide wayfinding and encourage movement throughout the space.


The interior design will be a neutral palette with complementary accent colors.





- Enhanced Indoor Air Quality
- Materials
 - Sourcing of Raw Materials
 - Recycled Content
 - EPD's & HPD's
 - Low Emitting Materials
- Interior Lighting
 - Artificial Lighting
 - Daylighting
- Acoustic Performance
































CAFETERIA









AUDITORIUM









RESTROOMS

Technical Performance

- Optimize Daylighting
- Maintain High Energy Efficiency
- Durability and Maintenance
- Recycled Content
- Acoustic Performance
- Low Emitting Materials

Cost Effectiveness

- Design for Repetition and Ease of Construction
- Prioritize Material Cost


Aesthetics

- Design for 21st Century Learning
- Express Educational Vision and Aspiration
- Timeless and Age Appropriate





CARPET TILE



BURNISHED CONCRETE







ACOUSTIC PANEL

ACCENT TILE



14 SEPTEMBER 2021



ACT/ WOOD LOOK METAL /

CEILINGS







CONCORD MIDDLE SCHOOL





FLOORING

WINDOWS

COUNTERS

CASEWORK/MILLWORK

BACK OF HOUSE

SOLID SURFACE/ EPOXY / LAMINATE

LAMINATE / WOOD

CMU / WALK OFF MAT













INTERIOR MATERIAL OPTIONS

				1			
	Burnished Concrete	Ceramic Tile	Carpet Tile	VCT	LVT	Rubber	Linoleum
Sizes / Format	Slab	File	Tile	Sheet or tile	Plank	Sheet or tile	Sheet or tile
Description	Structural slab with finish coating;	Ceramic tile, mortar;	carpet tile;	Vinyl composite tile; site applied top coat;	Luxury vinyl tile; factory- applied UV cured finish;	Natural rubber, no additional coating;	Linoleum tile; wax polish;
Refrence Manufacturer				Armstrong, Shaw	Armstrong, Shaw	Nora Sentico	Forbo, Armstrong
Cost/sf					<u> </u>		, , ,
FACTOR 1: PROGRAM CAPABILITY	Circulation	-	Media Center, Admin Office, Sensitive Sound	Corridor, Classrooms, Labs, Team Commons	Corridor, Classrooms, Labs, Team Commons	Corridor, Classrooms, Labs, Team Commons	Corridor, Classrooms, Labs Team Commons
Based on results of Life Cycle Assessment	Very good	Poor	Poor	Very poor	Poor	Good	Very good
	Makes use of structural	energy intensive		Much of impacts connected to coatings, stripper and polish	High levels of vinyl and urethane	Made from recycled materials, No Red List Chemicals	Bio-based material, low environmental impact in a categories
FACTOR 3: RED LIST CHEMICALS / TOXICITY Includes chemicals of concern & known carcinogens prohibited by project guidelines	Good	Good	Good	Poor	Poor	Good	Good
	No Red List Chemicals, VOC free coatings available	No Red List Chemicals, VOC ree	No Red List Chemicals, VOC free, Some concern for air quality/allergens from dust accumulation	, , , , ,	Contains high levels of phthalates, a Red List Chemical; coatings may pose VOC concerns	No Red List Chemicals, VOC free	No Red List Chemicals, VO free
FACTOR 4: DURABILITY Approximate life span based on manufacturer warrantee and Environmental Product Declaration (EPD)	Very good	/ery good	Poor	Poor	Good	Very good	Very good
	Full life of building, structural element	30 year life span; Difficult to replace broken :ile	10 year life span; Damaged tiles can be easily replaced	Damaged tiles can be easily replaced	20 year life span; More durable than VCT, resistant to divots; Damaged planks can be easily replaced	30 year life span; Damaged tiles can be easily replaced; Indentations occur, but rebound	30 year life span; Damageo tiles can be easily replaced Indentations occur, but rebound
FACTOR 5: MAINTENANCE	Low	.ow	Medium	High	Medium	Low	Medium
Required and recommended maintenance practices	None	No refinished required; potential discoloration of grout over time.	Requires vacuuming and Regular deep cleaning in high traffic areas.		Does not require stripping anc recoating, buffing and polish; Recommended for aesthetics.	No recoating required	Periodic recoating (wet mop/wax, no stripping); Recommended for aesthetics/shine.
FACTOR 6: LIFE CYCLE COST Tracked across 60 years cost/sq ft* material replacement (approx. maintenance cost, if relevant)	\$ tbd	\$ tbd	\$ tbd	•	\$ tbd	\$ tbd	\$ tbd
				(\$tbd/SqFt /yr maintenance)	(\$tbd/SqFt /yr maintenance)		(\$tbd/SqFt /yr maintenance)

 $\underset{\text{COLE}}{\overset{40}{\text{SMMA}}}$







41 Ewing SMMA






Wood Look Metal Ceiling

Exposed Metal Deck

Painted Gypsum Ceiling







Ceramic Tile Wainscot in Corridors

